

Baycruiser 23 Motor well



Sikaflex is applied to the hull between the laminae and marine ply. Removing the Sikaflex is difficult and can result in damaging the hull.

Baycruiser 23 Motor well



Laminae has been sandwiched between two thinned pieces of marine ply. This is then screwed into the 8mm Marine ply which is attached to the hull.

Bayraider 17 Motor well



I took this photo of the motor well inside a Bayraider 17. It would appear to be of a plastic material which is inserted and placed above the well. The laminae is glued/fixed to the underside of the plastic.